

Ford recalls Fusions; software causes key problem

November 18 2014



This Aug. 29, 2013 file photo shows a new 2014 Ford Fusion at the Flat Rock Assembly Plant in Flat Rock, Mich. Ford on Tuesday, Nov. 18, 2014 announced it is recalling about 65,000 2014 and 2015 model year Fusion midsize cars in North America because the ignition keys can be removed if the transmission is not in park. (AP Photo/Detroit News, Charles V. Tines, File)

Ford is recalling about 65,000 Fusion midsize cars in North America because the ignition keys can be removed if the transmission is not in

park due to a software problem.

The recall covers certain Fusions, including gas-electric hybrids, from the 2014 and 2015 model years. Ford traced the problem to a computer program in the instrument cluster. Keys can be removed 30 minutes after the ignition switch is turned off if the cars are left in gear. That violates U.S. safety regulations and increases the risk of cars rolling away unexpectedly.

Ford says it's not aware of any crashes or injuries from the problem. Dealers will reprogram the instrument cluster at no cost to owners.

The recall covers about 55,000 vehicles in the U.S., with the rest in Canada and Mexico.

© 2014 The Associated Press. All rights reserved.

Citation: Ford recalls Fusions; software causes key problem (2014, November 18) retrieved 28 April 2024 from <https://phys.org/news/2014-11-ford-recalls-fusions-software-key.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.
