

Boeing 737 MAX changes deemed 'operationally suitable': FAA

April 17 2019, by Luc Olinga With Heather Scott In Washington



Southwest Airlines and other carriers face a challenging summer after the entire fleet of Boeing 737 MAX aircraft were grounded

The changes US aircraft manufacturer Boeing has proposed in the wake of two deadly accidents of its top-selling 737 MAX aircraft were deemed "operationally suitable," according to a draft report released by



US regulators Tuesday.

However, Boeing has not yet submitted a planned software fix to the Federal Aviation Administration, the agency said in a statement.

Boeing has been working on a software fix for its anti-stall system following crashes in Ethiopia last month and Indonesia in October that killed nearly 350 people, both shortly after takeoff.

All 737 MAX <u>aircraft</u> have been banned from the world's skies since days after the Ethiopian Airlines crash on March 10, and the FAA has said it will not rush to approve the proposed fixes.

Crash investigators have zeroed in on the planes' anti-stall system, the Maneuvering Characteristics Augmentation System, or MCAS, which may have erroneously forced the planes down.


Boeing said it has been working on a software upgrade since late last year, and announced additional changes after last month's deadly crash.

The FAA said a Flight Standardization Board evaluated "the modified Maneuvering Characteristics Augmentation System (MCAS)" and said the "system was found to be operationally suitable."



MCAS and its latest fix

The Maneuvering Characteristics Augmentation System is an automated safety feature on Boeing's 737 MAX 8 designed to prevent the plane from entering into a stall



The MCAS system on 737 MAX 8 planes is designed to prevent engine stalls

'Aided instruction'

The report, which notes the differences in the MAX compared to prior



737 models, and any new training requirements, will be open for public comment for 14 days.

"After that, the FAA will review those comments before making a final assessment. Boeing Co. is still expected in the coming weeks to submit the final software package for certification," the agency said.

Because the 737 MAX is substantially similar to prior versions of the aircraft, pilots are not required to undergo extensive additional training, however the report added the MCAS to the list of items that require "aided instruction," such as videos or computer-based tutorials.

The grounding has put Boeing under increasing pressure, forcing it to halt deliveries of the aircraft. And US airlines are facing hundreds of daily flight cancelations through the summer, the peak travel season.

The MCAS was developed specifically for the 737 MAX, because its heavier engines created aerodynamic issues. But it apparently was designed to engage when alerted by a single sensor.

US pilots complained after the crash in October that they had not been fully briefed on the system.

The Ethiopian probe appeared to confirm suspicions about the MCAS, with data echoing that from the <u>crash</u> of the Indonesian Lion Air flight.

The full report has not been publicly released but, according to a draft copy seen by AFP, shortly after take-off a sensor recording the level of the plane began transmitting faulty data, prompting the autopilot system to point the nose downward.

© 2019 AFP



Citation: Boeing 737 MAX changes deemed 'operationally suitable': FAA (2019, April 17) retrieved 13 March 2024 from https://phys.org/news/2019-04-boeing-max-deemed-operationally-suitable.html

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.