

SpaceX aborts launch after 'odd' rocket engine behavior

February 18 2017



Space X's Falcon 9 rocket is prepared for launch to the International Space Station at the Kennedy Space Center, on a renovated Space Shuttle launch pads

SpaceX aborted its planned Dragon cargo launch to the International Space Station just seconds before liftoff Saturday due to a "slightly odd" technical issue with the Falcon 9 rocket engine.

The delay was made "out of an abundance of caution," a SpaceX

spokesman said, and came a day after engineers discovered a small helium leak in the engine's second stage.

"All systems go, except the movement trace of an upper stage engine steering hydraulic piston was slightly odd," SpaceX chief executive officer Elon Musk said on Twitter after the launch was scrubbed.

"Standing down to investigate."

Musk added that the issue was "99 percent likely to be fine."

"But that one percent chance isn't worth rolling the dice. Better to wait a day."

The next launch attempt is scheduled for 9:38 am Sunday (1438 GMT).

In the meantime, engineers plan to "take a closer look at the position of the second stage engine nozzle," SpaceX said.

The Hawthorne, California-based company has endured two costly disasters in the past two years—a launchpad blast that destroyed a rocket and its satellite payload in September, and a June 2015 explosion after liftoff that obliterated a Dragon cargo ship packed with provisions bound for the [space station](#).

SpaceX has since made one successful return to flight in January of this year, from Vandenberg Air Force base in California.

But this flight is particularly significant because of its starting point at Kennedy Space Center's launchpad 39A, used for the pioneering Apollo missions to the Moon in the 1960s and 1970s, and later for the space shuttle launches from 1981 to 2011.

SpaceX negotiated a lease for the launchpad with NASA in 2013, beating out its competitor Blue Origin, headed by Amazon founder Jeff Bezos.

By the time the launchpad is completely outfitted for sending astronauts to space in 2018, the company will have spent over \$100 million to adapt it for modern-day spaceflights, SpaceX chief operating officer Gwynne Shotwell said.

A report out this week by the US Government Accountability Office (GAO) found that the first crew flights by SpaceX and Boeing were likely to slip from 2018 to 2019 because of schedule delays and reduced budgets from Congress.

Since the US space shuttle program ended in 2011, the world's astronauts have relied on Russia's Soyuz capsules for transport to the space station.

Russia currently charges \$82 million per seat, the GAO said.

Asked by reporters Friday if SpaceX's Dragon V2 capsule for crew would be held back until 2019, Shotwell said: "I'm confident we will fly in 2018."

The current cargo resupply mission, known as CRS-10, is the 10th of up to 20 planned trips to the space station as part of a contract between SpaceX and NASA.

The unmanned spaceship is packed with more than 5,000 pounds (2,267 kilograms) of food, gear and science experiments for the astronauts living in orbit.

The weather forecast for Sunday is 70 percent favorable for liftoff.

Following the launch, SpaceX plans to try landing the booster on solid ground at a different part of Cape Canaveral.

If successful, the upright touchdown of the Falcon 9's first stage would mark the third time SpaceX has managed to stick a landing on solid ground.

Other such landings have taken place on floating ocean platforms, as the company perfects its techniques of powering costly rocket parts back to land instead of jettisoning them in the ocean after a single use.

© 2017 AFP

Citation: SpaceX aborts launch after 'odd' rocket engine behavior (2017, February 18) retrieved 1 May 2024 from <https://phys.org/news/2017-02-spacex-aborts-odd-rocket-behavior.html>

<p>This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.</p>
--