

'Clear similarities' between Boeing crashes in Ethiopia, Indonesia

March 18 2019, by Chris Stein



The FAA insists it followed standard procedures in certifying the Boeing 737 MAX

Flight recorder data recovered from the wreckage of Boeing 737 MAX planes that crashed in Ethiopia and Indonesia shows "clear similarities,"

Addis Ababa said Sunday as the US maker announced it was finalizing a software update for its under fire anti-stall system.

Pressure was mounting meanwhile on the US Federal Aviation Administration, which insisted it had followed standard procedures in certifying the plane model, even as it was reported to have come under investigation by the Department of Transport.

"The 737 MAX certification program followed the FAA's standard certification process," the agency said in an email to AFP.

It said its procedures were "well established and have consistently produced safe aircraft designs."

But reported similarities between the March 10 crash of an Ethiopian Airlines 737 Max 8, killing all 157 on board, and the Lion Air crash in October of the same model of plane in Indonesia, leaving 189 dead, have raised serious doubts and triggered Boeing's biggest crisis in decades.

The 737 MAX is a relatively new aircraft, having entered service only in May 2017 as Boeing's answer to Airbus's medium-haul A320 Neo.

Ethiopian Transport Minister Dagmawit Moges said Sunday that a study of the flight data recorder retrieved from the Ethiopian plane had shown "clear similarities" to that of the Lion Air flight in Indonesia.

She said the parallels would be the "subject of further study."

Pilots had complained

As investigators continue their work, preliminary findings in the Lion crash have focused on a possible malfunction of an anti-stall system known as the MCAS (Maneuvering Characteristics Augmentation

System).

Boeing developed that system, because of the unusually forward placement of the plane's engines, to avoid a stall.

The manufacturer said Sunday it was close to releasing a long-awaited software patch to the system.

"While investigators continue to work to establish definitive conclusions, Boeing is finalizing its development of a previously-announced software update and pilot training revision that will address the MCAS flight control law's behavior in response to erroneous sensor inputs," president and CEO Dennis Muilenburg said.

Experts have questioned the FAA's certification process after learning that American pilots had lodged serious complaints about the system.

According to a Wall Street Journal report Sunday, the FAA had come under an "unusual inquiry" by the Department of Transport over the issue, and has warned officials to safeguard computer files, according to sources quoted by the paper.



The March 10 crash of an Ethiopian Airlines 737 Max 8 shortly after takeoff from Addis Ababa killed all 157 on board

The Journal said the probe would zero in on Seattle-area FAA offices. Boeing airliners are built near Seattle.

A Seattle Times report Sunday said the FAA had delegated part of the certification process for the plane—including the MCAS—to Boeing engineers.

The original safety analysis provided to the FAA by Boeing contained "several crucial flaws," the newspaper said, adding that the process was carried out hastily as Boeing struggled to catch up with Airbus's more advanced work on the A320 Neo.

The report was dated 11 days before the Ethiopian Airlines accident, the newspaper reported.

'All requirements... met'

The FAA refused on Sunday to comment on the newspaper reports, noting the various investigations still under way.

In the face of budget cuts, the FAA since 2009 has delegated some certification work to aircraft manufacturers or to outside experts, a procedure known as ODA (Organization Designation Authorization).

On Sunday, the agency defended its practice, insisting that the 737 MAX had to pass multiple tests and reviews before being authorized to fly.

It said the aircraft's design was minutely examined, ground and flight tests were conducted, and other civil aviation authorities were consulted to ensure the "airplane complies with FAA standards."

A statement provided by Boeing to The Seattle Times said that "the FAA considered the final configuration and operating parameters of MCAS during MAX certification, and concluded that it met all certification and regulatory requirements."

It said, without elaborating, that there had been "some significant mischaracterizations" of the certification process.

Peter DeFazio, chairman of the House of Representatives' transportation and infrastructure committee, is planning to launch an investigation into the 737 MAX's certification, congressional sources said.

Michel Merluzeau, an analyst at AirInsight, urged a cautious process.

"There may be a need to re-examine what works and what does not work (in the certification process)—but it should not be done emotionally," Merluzeau said.

Another analyst, Richard Aboulafia of Teal Group, said the FAA's credibility is at stake—"as is Boeing's. And, the global system of aircraft certification reciprocity is at risk too," he said.

© 2019 AFP

Citation: 'Clear similarities' between Boeing crashes in Ethiopia, Indonesia (2019, March 18)
retrieved 20 April 2024 from

<https://phys.org/news/2019-03-black-similarities-indonesia-ethiopia.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.