

# Boeing astronaut capsule grounded for months by valve issue

August 14 2021, by Marcia Dunn



In this June 2, 2021 photo made available by NASA, technicians prepare Boeing's CST-100 Starliner for the company's Orbital Flight Test-2 (OFT-2) in the Commercial Crew and Cargo Processing Facility at NASA's Kennedy Space Center in Florida. On Friday, Aug. 13, 2021, Boeing and NASA officials said the capsule is grounded for months and possibly even until next year because of a vexing valve problem. Credit: NASA via AP

Boeing's astronaut capsule is grounded for months and possibly even until next year because of a vexing valve problem.

Boeing and NASA officials said Friday that the Starliner capsule will be removed from the top of its rocket and returned to its Kennedy Space Center hangar for more extensive repairs.

Starliner was poised to blast off on a repeat test flight to the International Space Station last week—carrying a mannequin but no astronauts—when the trouble arose. A similar capsule was plagued by software issues in 2019 that prevented it from reaching the [space station](#).

"We're obviously disappointed," said John Vollmer, [vice president](#) and program manager of Boeing's commercial crew program. "We will fly this test when we're ready to fly it and it's safe to do so."

Kathy Lueders, head of NASA's human exploration office, said it's "another example of why these demo missions are so very important to us ... to make sure we have the system wrung out before we put our crews on."

Boeing's performance is in stark contrast to that of SpaceX, NASA's other contracted taxi service. SpaceX has flown 10 astronauts to the space station in just over a year, with four more due to launch aboard the company's Dragon capsule at the end of October. Elon Musk's company will mark another first next month when it launches a billionaire into orbit with three guests, two of them contest winners.

Vollmer said moisture in the air somehow infiltrated 13 valves in the capsule's propulsion system. That moisture combined with a corrosive fuel-burning chemical that had gotten past seals, preventing the valves from opening as required before the Aug. 3 [launch attempt](#).

As of Friday, nine of the valves had been fixed. The other four require more invasive work.

Rain from a severe thunderstorm penetrated some of the capsule's thrusters at the pad, but engineers do not believe that is the same moisture that caused the valves to stick. Engineers are trying to determine how and when the moisture got there; it could have been during assembly or much later, Vollmer said.

The 13 in question are among dozens of valves that are tied into thrusters needed to get the capsule into the proper orbit and to the space station, and to also re-enter the atmosphere at flight's end. All the valves worked fine five weeks earlier and performed well in the 2019 test flight, Vollmer said.

Vollmer said it's too soon to know whether the valves will need to be replaced or even redesigned. Aerojet Rocketdyne supplied the valves, along with the rest of the propulsion system.

Given all the uncertainty, Vollmer was reluctant to say when Starliner might be ready for another launch attempt. Boeing will need to work around other [space](#) station traffic, as well as a NASA asteroid mission that's due to launch on the same kind of rocket from the same pad in October.

"Probably too early to say whether it's this year or not," Vollmer told reporters.

© 2021 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed without permission.

Citation: Boeing astronaut capsule grounded for months by valve issue (2021, August 14) retrieved 2 May 2024 from

<https://phys.org/news/2021-08-boeing-astronaut-capsule-grounded-months.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.