

Nuclear agency inspecting Maryland lab after contamination

28 September 2017

The Nuclear Regulatory Commission has begun a special inspection at a facility in suburban Maryland following a worker's potential exposure to radioactive contamination.

A five-member NRC team began the inspection Tuesday after an incident last month when a glass ampule containing americium-241 —a radioactive substance—broke in a National Institute of Standards and Technology laboratory used to prepare radioactive samples.

Test results indicated the employee potentially received a dose of radiation above NRC annual occupational limits. Additional testing is being done on the worker to determine the actual dose. The results will be included in a report to be issued within 45 days after the review is completed.

The NRC team is reviewing the circumstances surrounding the event as well as NIST's corrective actions.

Neil Sheehan, a spokesman for the NRC, said the occupational radioactive [exposure](#) estimated for the worker would not be expected to result in any immediate health effects. He said in an email that the exposure "marginally increases" the person's risk of developing cancer some time during his lifetime. He said further testing should clarify the estimated increased risk.

Jennifer Huergo, a spokeswoman for NIST, said the employee was treated at a hospital and released. She said the [worker](#) "received appropriate medical attention" based on guidance from specialists in radiation exposure care.

© 2017 The Associated Press. All rights reserved.

APA citation: Nuclear agency inspecting Maryland lab after contamination (2017, September 28) retrieved 25 September 2020 from <https://phys.org/news/2017-09-nuclear-agency-maryland-lab-contamination.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.