

Spacesuit problem mars ISS spacewalk

February 22 2007

Two International Space Station crewmembers successfully completed a 6-hour, 18-minute spacewalk Thursday despite a reported spacesuit malfunction.

Russian cosmonaut Mikhail Tyurin and U.S. astronaut Michael Lopez-Alegria left the space station at 5:27 a.m. and finished their work at 11:45 a.m. National Aeronautics and Space Administration controllers in Houston said the two men retracted a malfunctioning antenna on a Progress cargo carrier docked at the station and checked navigation systems in preparation for the summer docking of a European cargo craft.

The Russian news agency Interfax said Tyurin's Russian-made spacesuit's thermal regulation system apparently malfunctioned during the spacewalk. Tyurin said he felt cold when stepping into a shadow, suggesting there was a problem with the mechanism that controls the suit's temperature and humidity levels. The problem also caused fogging of the spacesuit's visor, NASA reported.

It was the fifth spacewalk for Lopez-Alegria and Tyurin during the current mission -- a record for ISS crews. The spacewalk was Lopez-Alegria's 10th, a U.S. record.

Copyright 2007 by United Press International

Citation: Spacesuit problem mars ISS spacewalk (2007, February 22) retrieved 26 April 2024 from <https://phys.org/news/2007-02-spacesuit-problem-mars-iss-spacewalk.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.