

# Sony warns its VAIO laptops may overheat, cause burns

June 30 2010

---



Sony Corp. Chairman and CEO Sir Howard Stringer shows a pocket-sized Sony Vaio computer during his keynote address at the 2009 International Consumer Electronics Show in Las Vegas. Japan's Sony issued a warning to customers worldwide that a system glitch affecting more than half a million of its VAIO laptop computers may cause overheating and possible burns.

Japan's Sony on Wednesday issued a warning to customers worldwide that a system glitch affecting more than half a million of its VAIO laptop computers may cause overheating and possible burns.

The electronics giant said a heat-monitoring chip in some of its VAIO F and C series models that were launched in January this year could be defective, leading to possible overheating, a company statement said.

Although the defect has not been known to cause personal injuries, the

firm said it received a total of 39 complaints from overseas customers saying that the shape of their computers became distorted from overheating.

The glitch affects a total of 535,000 laptops worldwide, of which nearly half is in the United States and the remainder in Japan, Europe and China.

Sony said it is offering consumers a [software application](#) download with which to correct the malfunction.

(c) 2010 AFP

Citation: Sony warns its VAIO laptops may overheat, cause burns (2010, June 30) retrieved 23 March 2023 from <https://phys.org/news/2010-06-sony-vaio-laptops-overheat.html>

<p>This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.</p>
--