

DARPA releases cause of hypersonic glider anomaly

April 21 2012, By JOHN ANTCZAK, Associated Press



This artists rendering provided by the U.S. Defense Advanced Research Projects Agency shows a Hypersonic Technology Vehicle-2, an unmanned hypersonic glider that likely aborted its 13,000 mph flight over the Pacific Ocean last summer because unexpectedly large sections of its skin peeled off, the U.S. Defense Advanced Research Projects Agency said Friday April 20, 2012. (AP Photo/DARPA)

(AP) -- An unmanned hypersonic glider likely aborted its 13,000 mph flight over the Pacific Ocean last summer because unexpectedly large sections of its skin peeled off, the U.S. Defense Advanced Research



Projects Agency said Friday.

The Hypersonic Technology Vehicle-2, launched from Vandenberg Air Force Base, Calif., atop a rocket and released on Aug. 11, 2011, was part of research aimed at developing super-fast global strike capability for the Department of Defense.

The vehicle demonstrated stable aerodynamically controlled flight at speeds up to 20 times the speed of sound, or Mach 20, for three minutes before a series of upsets caused its autonomous flight safety system to bring it down in the ocean, DARPA said in a statement.

A gradual wearing away of the vehicle's skin was expected because of extremely high temperatures, but an independent engineering review board concluded that the most probable cause was "unexpected aeroshell degradation, creating multiple upsets of increasing severity that ultimately activated the Flight Safety System," the statement said.

Initial shockwaves created by the gaps in the skin were more than 100 times what the vehicle was designed to withstand, but it was still able to recover and return to controlled flight, said Kaigham J. Gabriel, DARPA's acting director.

Eventually the upsets grew beyond its ability to recover.

The 2011 flight was the second time an HTV-2 was launched. The first flight, in April 2010, also ended prematurely.

Data from that flight was used to correct aerodynamic design models for the second test, resulting in controlled flight, and now data from the latest flight will be used to adjust assumptions about thermal modeling, Air Force Maj. Chris Schulz, the DARPA program manager, said in the statement.



"The result of these findings is a profound advancement in understanding the areas we need to focus on to advance aerothermal structures for future hypersonic vehicles. Only actual flight data could have revealed this to us," he said.

Most specific details of the program are secret. DARPA has released artist renderings showing a craft that looks something like the tip of a spear. After the 2011 flight the agency released handheld video, taken aboard a monitoring ship, that showed a dot streaking across the sky.

The HTV-2 would have splashed down in the ocean regardless of the anomaly. The vehicles are intended to be used once and are not recovered.

©2012 The Associated Press. All rights reserved. This material may not be published, broadcast, rewritten or redistributed.

Citation: DARPA releases cause of hypersonic glider anomaly (2012, April 21) retrieved 24 June 2024 from https://phys.org/news/2012-04-darpa-hypersonic-glider-anomaly.html

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.