

First crewed flight of Boeing Starliner postponed again

May 18 2024



Credit: Pixabay/CC0 Public Domain

The first crewed launch of Boeing's Starliner to the International Space Station has been delayed again due to a technical issue, NASA said Friday.

The launch in Florida was scheduled for Tuesday but NASA said it is now planned for May 25 to allow teams to further assess a helium leak linked to the [service module](#), which sits on top of the rocket.

Earlier this month, a Starliner launch was postponed just hours before lift-off, with the astronauts already strapped in, due to a separate technical issue.

"The additional time allows teams to further assess" the helium leak, NASA said on its website.

The two astronauts, Butch Wilmore and Suni Williams, are in the meantime staying in Houston, Texas until the mission is ready.

It is another delay in the highly anticipated mission which has faced years of delays and comes at a challenging time for Boeing, as safety questions surround the century-old aerospace titan's commercial aviation arm.

NASA is banking on Starliner's success for its goal of certifying a second commercial vehicle to carry crews to the International Space Station.

Elon Musk's SpaceX already achieved this in 2020 with its Dragon capsule, ending a nearly decade-long dependence on Russian rockets following the end of the Space Shuttle program.

© 2024 AFP

Citation: First crewed flight of Boeing Starliner postponed again (2024, May 18) retrieved 3 June 2024 from <https://phys.org/news/2024-05-crewed-flight-boeing-starliner-postponed.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private

study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.