

# Space station cooling normally after spacewalk fix

18 August 2010, By MARCIA DUNN , AP Aerospace Writer

---

rewritten or redistributed.



In this photo taken from NASA television, Expedition 24 astronauts work outside the space station, Monday, Aug. 16, 2010. (AP Photo/NASA)

(AP) -- The International Space Station is operating normally again following a series of spacewalking repairs.

The crew installed a new ammonia coolant pump Monday. That enabled flight controllers to activate the coolant loop that was knocked offline July 31st.

The orbiting lab needs two functioning cooling lines to keep on-board electronics from overheating.

[NASA](#) said Wednesday that all of the equipment that was turned off following the breakdown is running again. Science research should resume Thursday.

The two U.S. [astronauts](#) who performed the three spacewalks got some time off Wednesday. On Thursday, they will remove a jumper cable that provided cooling to equipment on the Russian side.

©2010 The Associated Press. All rights reserved.  
This material may not be published, broadcast,

APA citation: Space station cooling normally after spacewalk fix (2010, August 18) retrieved 11 May 2021 from <https://phys.org/news/2010-08-space-station-cooling-spacewalk.html>

*This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.*