

# Feds probe VW air bags after inflator ruptures in Missouri

18 August 2015, by Tom Krisher



This photo provided by Volkswagen shows a 2015 VW Tiguan. A June 7, 2015 collision between the Volkswagen SUV and a deer in which a side air bag inflated with too much force has triggered a federal investigation and raised questions about the safety of newer air bags made by Takata Corp. of Japan. In the crash near St. Louis, the left side air bag inflated in a 2015 VW Tiguan, blowing apart a metal canister. It's the first incident reported in a VW, the first in a side air bag, and the first in the field involving newer versions of Takata air bags. (Volkswagen via AP)

A June collision between a Volkswagen SUV and a deer in which a side air bag inflated with too much force has triggered a federal investigation and raised questions about the safety of newer air bags made by Takata Corp. of Japan.

In the June 7 crash near St. Louis, the left side air bag inflated in a 2015 VW Tiguan, blowing apart a metal canister. It's the first incident reported in a VW, the first in a side air bag, and the first in the field involving newer versions of Takata air bags. Previously Takata has said the problem was limited to older designs in front and passenger air bags.

Volkswagen told the National Highway Traffic

Safety Administration about the crash on July 15, and the agency began investigating. Last week it sent orders to Takata and VW seeking information on the crash and air bag tests. Both have until Aug. 24 to reply.

The investigation calls into question whether all air bag systems made with ammonium nitrate, the chemical that Takata uses as a propellant to inflate its bags, should be recalled, said Karl Brauer, senior auto industry analyst for Kelley Blue Book. Although the Tiguan problem could be an isolated manufacturing problem, Brauer says with Takata's history, it's possible that more recalls involving more vehicle brands are coming.

"It's a scary thing," Brauer said. "Are we still seeing the tip of the iceberg here?"

Takata and VW said they are cooperating in the investigation, and Takata said it doesn't believe the Tiguan case is related to any previous incidents.

In May, Takata bowed to U.S. government pressure and agreed to double the number of air bag inflators it's recalling to 33.8 million, making it the largest automotive recall in U.S. history. The problem, which has persisted for more than a decade, has brought congressional hearings and investigations from NHTSA and the Justice Department. Worldwide, 11 automakers have recalled about 57.5 million vehicles with Takata air bags.

At least eight deaths and more than 100 injuries have been attributed to the air bag inflator ruptures.

VW spokesman Mark Gillies said the company is working with NHTSA and Takata to better understand the situation. The Tiguan driver did not seek medical attention, although Gillies did not know if he was cut by flying shrapnel from the inflator. Gillies said there have been no other incidents of air bag inflators rupturing in VW

vehicles. He said he didn't know how many other VW vehicles have Takata air bags or for how long the company has used Takata air bags.

"While we are still investigating the cause of this malfunction, we believe it is unrelated to the previous recalls, which the extensive data suggests were a result of aging and long-term exposure to heat and high humidity," Takata's statement said.

Takata uses ammonium nitrate to create a small explosion and quickly inflate air bags. But the chemical can become unstable when exposed to airborne moisture, burning too fast and blowing apart a metal canister designed to contain the explosion. Takata says most of the problems have happened in areas with high humidity, mainly along the U.S. Gulf Coast.

In its orders to VW and Takata, NHTSA is looking to see if the problem is broader than the previous recalls. The order to Takata seeks a report identifying every air bag inflator made by the company that used ammonium nitrate. The VW order asks for a list of all vehicles ever made by the company with air bag inflators that used ammonium nitrate as a propellant. It also asks for failure rates of all side air bags in tests done by the company or third parties.

Of the vehicles under recall for Takata air bag problems, the newest are from the 2011 model year.

© 2015 The Associated Press. All rights reserved.

APA citation: Feds probe VW air bags after inflator ruptures in Missouri (2015, August 18) retrieved 17 September 2019 from <https://phys.org/news/2015-08-feds-probe-vw-air-bags.html>

*This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.*