


NASA shows first 'crime scene' photo of Mars landing

August 7 2012, by Kerry Sheridan



The four main pieces of hardware that arrived on Mars with NASA's Curiosity rover were spotted by NASA's Mars Reconnaissance Orbiter (MRO). The High-Resolution Imaging Science Experiment (HiRISE) camera captured this image about 24 hours after landing. The large, reduced-scale image points out the strewn hardware: the heat shield was the first piece to hit the ground, followed by the back shell attached to the parachute, then the rover itself touched down, and finally, after cables were cut, the sky crane flew away to the northwest and crashed. Relatively dark areas in all four spots are from disturbances of the bright dust on Mars, revealing the darker material below the surface dust. Around the rover, this disturbance was from the sky crane thrusters, and forms a

bilaterally symmetrical pattern. The darkened radial jets from the sky crane are downrange from the point of oblique impact, much like the oblique impacts of asteroids. In fact, they make an arrow pointing to Curiosity. This image was acquired from a special 41-degree roll of MRO, larger than the normal 30-degree limit. It rolled towards the west and towards the sun, which increases visible scattering by atmospheric dust as well as the amount of atmosphere the orbiter has to look through, thereby reducing the contrast of surface features. Future images will show the hardware in greater detail. Our view is tilted about 45 degrees from the surface (more than the 41-degree roll due to planetary curvature), like a view out of an airplane window. Tilt the images 90 degrees clockwise to see the surface better from this perspective. The views are primarily of the shadowed side of the rover and other objects. The image scale is 39 centimeters (15.3 inches) per pixel. Image credit: NASA/JPL-Caltech/Univ. of Arizona

About 36 hours after NASA landed its \$2.5 billion rover on Mars, it released Tuesday what it jokingly dubbed a "crime scene" aerial shot of where the parachute, heat shield and vehicle came down.

The touchdown on August 6 of the Mars Science Laboratory involved the most elaborate attempt yet to drop a robotic car on the surface of the Red Planet, and required a heat shield, supersonic parachute and rocket-powered sky crane.

The process, known as entry, descent and landing, or EDL, was referred to as "Seven Minutes of Terror" by NASA, but went off without a hitch, in what US President Barack Obama called an "unprecedented feat of technology."


On approach, a heat shield protected the Curiosity rover's fiery entry into Mars' atmosphere, a supersonic parachute deployed to slow it down, and the spacecraft back shell separated.

Then, a rocket powered backpack was fired to power the one-ton rover downward before it was lowered by nylon tethers. The sky crane was designed to detach and fly away to crash somewhere to the north.

The latest black and white picture released Tuesday was taken by the Mars Reconnaissance Orbiter as it flew about 300 kilometers (185 miles) above the landing site of Gale Crater, near Mars' equator.

It shows the Mars Science Laboratory rover, nicknamed Curiosity, with the now defunct sky crane about 650 meters (yards) away to the northwest.

The parachute and backshell of the spacecraft that separated before it lowered down landed about 615 meters away from the rover to the southwest.



Graphic on NASA's Mars Science Laboratory landing, as well as previous touchdowns for rovers and landers on the Red Planet.

The heat shield appears to be about 1,200 meters from the rover to the southeast.

"This is like a crime scene photo here," said Sarah Milkovich, a NASA scientist who is the lead investigator of the HiRISE camera on the Mars orbiter.

"Hopefully in our future images we be able to get even better, more detail," she said, adding that the dark areas in the photo show where dust was kicked up during the landing.

The EDL team has reviewed the latest photos and said "the layout looks kind of the way they expected," according to mission manager Mike Watkins.

The pieces will likely stay on Mars. There are no plans to recover them to bring back to Earth.

NASA is continuing to run tests on the various instruments on board the rover, which aim to help hunt for signs that life may once have existed on Earth's neighbor planet, once believed to be a wetter place than it is today.

So far most of the checks have gone well and the rover appears to be in good shape.

On Wednesday, NASA plans to lift the rover's remote sensing mast for the first time. More images, including color high-resolution shots, are

expected to arrive in the coming days.

But the rover is not expected to start moving for several more weeks, and it may be a year before it reaches its scientific target of Mount Sharp.

Deputy project scientist Joy Crisp said the latest analysis shows that the rover is 6.5 kilometers from the base of the mountain, if it were to travel straight there.

However, scientists have warned it is difficult to estimate the exact start of the base and they have no plans to drive to it directly, but will likely take a more meandering route.

The Mars Science Laboratory is a nuclear-powered vehicle that is designed for a two-year robotic mission on Mars, though scientists hope it will last as least twice its original design life.

(c) 2012 AFP

Citation: NASA shows first 'crime scene' photo of Mars landing (2012, August 7) retrieved 23 June 2024 from <https://phys.org/news/2012-08-nasa-crime-scene-photo-mars.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.