

High radiation detected at Fukushima monitoring well: reports

September 9 2013



This handout picture taken by Tokyo Electric Power Co (TEPCO) on September 4, 2013 shows a TEPCO worker checking radiation around the contamination water tank at TEPCO's Fukushima Dai-ichi nuclear power plant at Okuma town in Fukushima prefecture.

The operator of Japan's stricken Fukushima nuclear plant on Monday said that groundwater from an observation well near the site of a leaky storage tank showed high levels of radiation, according to reports.

The finding means that it "now seems more likely" that [radioactive water](#) from leaking tanks had mixed with [groundwater](#) in the area, Jiji press and Kyodo news agency quoted the Tokyo Electric Power Company (TEPCO) as saying.

Many of the tanks were used to cool molten [reactors](#) wrecked by an earthquake and tsunami disaster in March 2011.

The well was found to have contained 3,200 becquerels per litre of beta-ray emitting materials, including strontium.

Last week, the Japanese government unveiled a half-billion dollar plan to stem the leaks by creating a wall of ice under the plant.

TEPCO also plans to use wells to pump up the groundwater before it seeps into the sea.

But, according to Kyodo news, the latest findings could affect that plan as the nearest pumping well is only 130 metres (140 yards) away from the monitoring site from where the sample was taken.

© 2013 AFP

Citation: High radiation detected at Fukushima monitoring well: reports (2013, September 9) retrieved 23 May 2024 from <https://phys.org/news/2013-09-high-fukushima.html>

<p>This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.</p>
--