


# Image: Sentinel-1 sees Mocoa landslide

April 5 2017

---



Credit: contains modified Copernicus Sentinel data (2017), processed by I. Parcharidis, Harokopio University of Athens

Sentinel-1 radar coverage from before and after the 1 April 2017

mudslide in Mocoa, Colombia, shows the extent of movement of the disaster that claimed over 260 lives, injured hundreds more and left scores displaced.

Triggered by heavy rain, the landslide caused greatest movement (red) on top of a mountain. It then pushed mud down across the city of Mocoa (green) and crossed the nearby river.

Sentinel-1's [radar](#) ability to 'see' through clouds, rain and in darkness makes it particularly useful for monitoring areas with frequent cloud cover. Images acquired before and after events such as floods, landslides or earthquakes offer immediate information on the [extent](#) of affected areas and support assessments of property and environmental damage.

The Sentinel-1-derived data product (from scans on 20 March and 1 April) has been overlaid onto a Sentinel-1 radar image. Sentinel-1 is a two-satellite mission for Europe's Copernicus environment monitoring programme.

Provided by European Space Agency

Citation: Image: Sentinel-1 sees Mocoa landslide (2017, April 5) retrieved 26 April 2024 from <https://phys.org/news/2017-04-image-sentinel-mocoa-landslide.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.