

# Chernobyl's radiation monitoring hit by cyberattack: spokeswoman

June 27 2017

---



This photo taken on April 22, 2016 shows the 4th block of Chernobyl's Nuclear Power Plant (R) and Chernobyl's New Safe Confinement (L)

The radiation monitoring system at Ukraine's Chernobyl nuclear site has been taken offline after a massive cyberattack, forcing employees to use hand-held counters to measure levels, officials said Tuesday.

"Due to the cyberattack, the website of the Chernobyl nuclear plant is

not working," said Ukraine's exclusion zone agency which oversees the Soviet plant that exploded in 1986 and is now surrounded by an uninhabited contaminated zone.

"Due to the temporary shutdown of the Windows system, the radiation monitoring of the industrial area is being done manually," the agency said on its website.

"That means that our measurers go out with hand-held meters on the Chernobyl plant like it was decades ago," a spokeswoman for the agency, Olena Kovalchuk, told AFP.

The plant's destroyed reactor was enclosed in a huge metal structure last year in a bid to stop [radiation leaks](#) at the site, where more than 200 tonnes of uranium remain.

Ukraine, along with Russia and companies across Europe, was hit Tuesday in a wave of cyberattacks which IT experts identified as a modified version of the Petya ransomware that struck last year.

Ukraine's exclusion zone agency said that Chernobyl's "technological systems are working as usual" and that [radiation](#) control is "without delays".

© 2017 AFP

Citation: Chernobyl's radiation monitoring hit by cyberattack: spokeswoman (2017, June 27) retrieved 13 June 2024 from <https://phys.org/news/2017-06-chernobyl-cyberattack-spokeswoman.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.